

PRODUCT UPDATE



Item	ML-Flexi-Link
Update #	1
Date	Dec 9, 2010

DESCRIPTION:

The newer version of the Flexi-Link pole is bent three degrees at the top.

RATIONALE:

Some caregivers may forget to remove the Flexi-Link after using it to hook the Nomad to the trolley.

In that situation, the original straight pole might potentially hit against the Nomad and damage its case.

The slight bent of the pole in the updated version helps to prevent this issue from occurring.